

## Filename Extension Summary

Top Copper	Bottom Copper	Top Soldermask	Bottom Soldermask
.TOP .CMP .GTL .LY1 art01.pho	.BOT .SOL .GBL .LY2 art02.pho	.MSK .STC .SMT .GTS .GTM .MK1 .TMK .TSM .SM1 sm01.* sm0128.pho	.STS .SMB .MK2 .BMK .GBS .GBM .BSM .SM2 sm02.* sm0228.pho

Top Silkscreen	Bottom Silkscreen	NC Drill	Inner Layers
.GTO .OVL .SLK .SK1 .SS1 .TSK .PLC sst0126.pho	.GBO .BSK .PLS .SK2 .SS2 ssb01 ssb0226.pho	.TAP .TXT .DRL .NCD .DRD .TH thruhole.*	.SIG .G1 .P1 .GP1 .GND .PWR .L1 plane.* art.* .GM1

Fab Print
.DD1 .DRD art.* fab.* print.* .DWG

### NOTES:

- .TXT may be drill file but could also be readme file
- .DRD may be drill file but is sometimes also fab drawing
- .GM1 is usually a mechanical layer but can sometimes be inner layer.
- .GKO is a "keep out" layer note -- do NOT use, not even for board dimensions.